7 - EQUIPMENT:

3

5

The equipment associated with the cause of the Rice Fire was a 12 KV distribution line operated by San Diego Gas and Electric. The effected span was between Pole #112340 and Pole #213072. Sections of the effected power line were collected as evidence, Items #1-4.